

C.O.C:

REPORT No: B20-35250

Report To:
Environmental
 5 Binnington Crt.
 Kingston, ON

Caduceon Environmental Laboratories
 285 Dalton Ave
 Kingston, Ontario K7K 6Z1
 Tel: 613-544-2001
 Fax: 613-544-2770

Attention: Tom Poffley

DATE RECEIVED: 6-Nov-20
 DATE REPORTED: 9-Nov-20
 SAMPLE MATRIX: S

JOB/PROJECT NO.: William St
 P.O. NUMBER:

Client I.D.	Lab Sample I.D.	Description Location	Date Collected	Sample Appearance	SAMPLE COMPONENTS (%)			
					Asbestos Fibres		Non - asbestos Fibres	Non - fibrous Material
Wall Cav.	35250-1		6-Nov-10	Brown/Beige/Gold	1.0%	Actinolite	0.0%	99.0%

None Detected = <0.1%. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP of any agency of the U.S. Government.

Samples analyzed by EMSL Canada Inc. Ottawa, ON



Michelle Dubien
 Lab Manager

Vermiculite insulation was found in the wall at the first floor living room staircase behind the first floor shower stall. A sample was taken and sent to a lab for testing and returned positive for containing trace amounts of asbestos. The inspector was not able to find any vermiculite insulation in any other accessible walls and he confirmed there is only fiberglass insulation (no vermiculite) in the attic.