



ST 5111

COBRA POSE

APPLICATION INSTRUCTIONS

SIZE


approx. 4 feet 5 inches wide x
4 feet 4 inches long

PAINTERS & TIME

1-2 painters for less than 1 hr



INCLUDED IN THE BOX: 1 Stencil Sheet (3 pieces)



BEFORE YOU START PAINTING: Please completely read the General Instructions & prepare your surfaces as recommended.



STEP 1:

Separate the stencil pieces along the perforation. Rotate the illustration stencil piece clockwise.

Layout your **STENCIL** in your desired location.

**You can put the words above, or to the left/right of the illustration.



STEP 2:

Paint your **STENCIL**. Repeat 1-2 more times to achieve desired vividness, drying after each application. Then remove your **STENCIL**. Fill in the gaps so your **STENCIL** is complete.

Allow the paint to dry for a minimum of 24 hours before use.

CONGRATULATIONS!!!

**YOU FINISHED PAINTING COBRA POSE
YOU DID IT! GIVE YOURSELVES A PAT ON THE BACK!**

Your finished Cobra Pose should look like the image below.



Have any questions? We're here to help – call us at (800) 681-0684!

VISIT OUR WEBSITE AT WWW.FITANDFUNPLAYSCAPES.COM