



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.: **DE/EPS/QAR14.0001/06** Page 1 of 1

QAR Free Ref. No.: **20TH0059** Status: **Issued**

Details of change: **Renewal audit completed** Date of issue: **2020-01-13**

Site(s) audited: **IDENTEC SOLUTIONS AG** Valid until: **2023-01-09**  
Millenium Park 2  
6890 Lustenau  
**Austria** Audit date: **2020-01-10**

Issuing ExCB: **EPS - Bureau Veritas Consumer Products Services Germany GmbH**

Manufacturer: **IDENTEC SOLUTIONS AG**  
Millenium Park 2  
6890 Lustenau

Location of  
Manufacturer: **Austria**

Product information: **Electrical and electronic products.**

Protection concept: **i**

Related QARs:

<b>DE/EPS/QAR14.0001/00</b>	<b>DE/EPS/QAR14.0001/01</b>	<b>DE/EPS/QAR14.0001/02</b>
<b>DE/EPS/QAR14.0001/03</b>	<b>DE/EPS/QAR14.0001/04</b>	<b>DE/EPS/QAR14.0001/05</b>

Related Certificates  
(manual insertion): **IECEX DNV 08.0006**  
**IECEX DNV 08.0004X**  
**IECEX DNV 08.0005**  
**IECEX EPS 13.0018X**

Related Certificates  
(automatic linking):

Related Certificates for  
previous versions:

<b>IECEX EPS 13.0018X issue: 1</b>	<b>IECEX EPS 14.0012X issue: 0</b>	<b>IECEX EPS 14.0012X issue: 1</b>
<b>IECEX EPS 14.0012X issue: 2</b>	<b>IECEX EPS 14.0032X issue: 0</b>	<b>IECEX EPS 14.0034 issue: 0</b>
<b>IECEX EPS 14.0078X issue: 0</b>	<b>IECEX EPS 14.0096 issue: 0</b>	<b>IECEX EPS 15.0006X issue: 0</b>
<b>IECEX EPS 15.0058X issue: 0</b>	<b>IECEX EPS 16.0035 issue: 0</b>	<b>IECEX EPS 18.0035 issue: 0</b>
<b>IECEX EPS 19.0010X issue: 0</b>		

Comments: