



# IECEX Facility Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

FAR Ref. No.: **GB/SIR/FAR21.0002/00**

Page 1 of 1

Issuing ExCB: **SIR - SIRA Certification Service**

Date of issue: : **2021-03-29**

Status : **Issued**

Audit date:

**2021-01-07**

Valid Until:

**2024-01-07**

Site audited:

**Matric Limited**  
2099 Hill City Road  
Seneca  
PA 16346  
USA  
**United States of America**

Service Facility:

**Matric Limited**  
2099 Hill City Road  
Seneca  
PA 16346  
USA  
**United States of America**

Type of work Covered **Repair and overhaul of Group 1 Mining Equipment**  
by Service Facility:

Related FARs:

Related IECEx Service  
Facility Certificates:

[IECEX SIR S0032 Issue 0](#)

Comments: